## IN THE UNITED STATES PATENT & TRADEMARK OFFICE

ATTORNEY DOCKET NUMBER: 10006165-1

IN RE APPLICATION OF: U.S. Patent No. 6,955,976

USPTO CONFIRMATION CODE: 5663

APPLICATION NO.: 10/066,213

FILED: Feb 01, 2002

EXAMINER: George Fourson

**GROUP ART UNIT: 2823** 

FOR: METHOD FOR DICING WAFER STACKS TO PROVIDE ACCESS TO INTERIOR STRUCTURES

## 37 CFR 1.322 & 37 CFR 1.323 REQUEST FOR CERTIFICATE OF CORRECTION

## HONORABLE COMMISSIONER OF PATENTS & TRADEMARKS

Sir:

The following is a request for a certificate of correction in Serial Number 10/066.213, now Patent Number 6,955,976.

A certificate of correction under 35 USC 254 is respectfully requested in the above-identified patent.

X	All errors were the fault of the USPTO, no fee required. In the event that a	further
	required, please charge the amount to Deposit Account No. 082025.	

All errors were the fault of the applicant and, accordingly, please charge \$100.00 to our Deposit Account No. 082025. In the event that a further fee is required, please charge the amount to the same Deposit Account.

The errors were the fault of both the applicant and USPTO and, accordingly, please charge \$100.00 to our Deposit Account No. 082025. In the event that a further fee is required, please charge the amount to the same Deposit Account.

The exact locations where the errors appear in the patent and patent application are as follows:

On the face page, in field (54), in "Title", in column 1, line 1, delete "METHOD" and insert - - METHODS - -, therefor.

(Request for Corrected Filing Receipt filed on Mar. 18, 2002, page 1, line 13)

In column 1, line 1, delete "METHOD" and insert - - METHODS - -, therefor. (Request for Corrected Filing Receipt filed on Mar. 18, 2002, page 1, line 13)

In column 8, line 14, in Claim 5, delete "compnses:" and insert - - comprises: - -, therefor.

(Amendment to claims filed on Nov 12, 2004, page 4, in Claim 7, line 15)

The requested corrections are attached on Form PTO 1050.

Respectfully Submitted

Name: Douglas M. Gilbert Registration No.: 27, 196

Attorney/Agent of Record

HEWLETT-PACKARD COMPANY Intellectual Property Administration 3404 E. Harmony Road Mail Stop 35

Fort Collins, CO 80528

## UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

Page 1 of 1

PATENT NO. : 6,955,976

APPLICATION NO. : 10/066,213

ISSUE DATE : Oct. 18, 2005

INVENTOR(S) : Peter G. Hartwell, et al.

It is certified that an error appears or errors appear in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

On the face page, in field (54), in "Title", in column 1, line 1, delete "METHOD" and insert - METHODS - -, therefor.

In column 1, line 1, delete "METHOD" and insert - - METHODS - -, therefor.

In column 8, line 14, in Claim 5, delete "compnses:" and insert - - comprises: - -, therefor.

MAILING ADDRESS OF SENDER (Please do not use customer number below):

HEWLETT-PACK ARD COMPANY Intellectual Property Administration 3404 E. Harmony Road Mail Stop 35 Fort Collins, CO 80528

This collection of information is required by 37 CFR 1322, and 1323, and 1324. The information is required to obtain or retain a beautiful by the public value in the first of the first